




FOR CSA-GND KIT

- 1/2-IN CONDUIT
- 3/4-IN CONDUIT
- 1-IN CONDUIT
- 1 1/4-IN CONDUIT
- 1 1/2-IN CONDUIT
- 2-IN CONDUIT
- 2 1/2-IN CONDUIT

- 55-213403G001
- 55-213403G002
- 55-213403G003
- 55-213403G004
- 55-213403G005
- 55-213403G004
- 55-213403G005



NOMENCLATURE


- CL - CLOSING COIL
- CR - CONTROL RELAY
- F1,F2- OPTIONAL FUSING
- I- INDICATING LIGHTS
- OP - OPENING COIL
- PB - PUSHBUTTON
- PD - PILOT DEVICE
- SS - SELECTOR SWITCH
- PTT-PUSH TO TEST
- * - WHEN ORDERED

LOAD

RATING	LB-IN
30A	30
60A	50
75A	50
100A	50
150A	250
200A	250
225A	250

USE 75°C, COPPER CONDUCTORS ONLY. FOR FIELD WIRING. TORQUE LINE AND LOAD TERMINALS AS SHOWN AT RIGHT:

NOTE: WIRE "B" MUST BE REMOVED FROM L2 AND RETURNED TO NEUTRAL FOR NON-STANDARD LINE TO NEUTRAL VOLTAGE CONNECTIONS.



imagination at work

WIRING DIAGRAM
CR160MC LIGHTING CONTACTOR

AN #	THIRD ANGLE PROJECTION	SHEET #
09-9114		1 OF 1

DWG NO.	DATE	REV
55-186547	08/26/2009	2