



-NOMENCLATURE-
 I-INDICATING LIGHT
 OL-OVERLOAD
 *-IF ORDERED
 SW 1- ON OFF STARTER
 SW 2- AUTO HAND SWITCH

NOTE: ADDITIONAL OVER-CURRENT PROTECTION
 MAY BE REQUIRED. REFER TO THE
 NATIONAL ELECTRICAL CODE OR LOCAL
 ELECTRICAL CODE AS REQUIRED.

USE 75°C COPPER CONDUCTORS ONLY,
 FOR FIELD WIRING. TORQUE LINE AND
 LOAD TERMINALS TO 20 LB. IN.



WIRING DIAGRAM
 CR101H

AN #	THIRD ANGLE PROJECTION	SHEET #
09-9107		1 OF 1

DWG NO.	DATE	REV
55-206782	08/03/2009	2